



**BP 249 Z. I.
44 158 ANCENIS CEDEX FRANCE
TEL : +33 (0)2 40 09 10 11**

YOUR CONCESSIONAIRE

REF : 547 357 EN (05 / 04)

**ACCESS
PLATFORM
80 VJR
105 VJR2
REPAIRS MANUAL**

1st EDITION**07 / 2002**

ISSUE DATE	COMMENTS
07/2002	1st edition
01/2004	Updated
05/2004	Updated 70-5-M.85 70-6-M.85 80-8-11-M.85 80-8-85-M.85

CONTENTS

GROUPS	SECTIONS	MACHINES
0	General points	
0-1-M.85 EN	Technical characteristics	80 VJR / 105 VJR2 0-1-M.85
30	Wheel motor	
30-2-70-M.85 EN	Removing the wheel motors	80 VJR / 105 VJR2 30-2-70-M.85
35	Steering axle	
35-8-21-M.85 EN	Freewheeling	80 VJR / 105 VJR2 35-8-21-M.85
55	Arms - Platform	
55-2-21-M.85 EN	Removing the telescope wear pads	80 VJR / 105 VJR2 55-2-21-M.85
70	Hydraulics	
70-2-52-M.85 EN	Removing the distributor elements	80 VJR / 105 VJR2 70-2-52-M.85
70-2-80-M.85 EN	Removing the cylinders	80 VJR / 105 VJR2 70-2-80-M.85
70-5-M.85 EN	Hydraulic pressure	80 VJR / 105 VJR2 70-5-M.85
70-6-M.85 EN	Hydraulic layout	80 VJR / 105 VJR2 70-6-M.85
80	Electricity	
80-2-11-M.85 EN	Removing the variable speed drive unit	80 VJR / 105 VJR2 80-2-11-M.85
80-2-12-M.85 EN	Removing the traction batteries	80 VJR / 105 VJR2 80-2-12-M.85
80-2-13-M.85 EN	Removing the electrical cable looms	80 VJR / 105 VJR2 80-2-13-M.85
80-6-M.85 EN	Electrical layouts	80 VJR / 105 VJR2 80-6-M.85
80-8-11-M.85 EN	Checking the operation of the Sevcon variable speed drive	80 VJR / 105 VJR2 80-8-11-M.85

CONTENTS

GROUPS	SECTIONS	MACHINES
80-8-85-M.85 EN	Testing the manipulator	80 VJR / 105 VJR2 80-8-85-M.85
80-8-86-M.85 EN	Positioning and adjusting the contactors	80 VJR / 105 VJR2 80-8-86-M.85
100	Troubleshooting	
100-M.85 EN	Troubleshooting	80 VJR / 105 VJR2 100-M.85

GROUPS 0

***GENERAL
POINTS***

TECHNICAL CHARACTERISTICS
80 VJR / 105 VJR2
0-1-M.85 EN

0-1-M.85

Manitou Access Platform 80 105vjr Service Sec Wat

Full download: <http://manualplace.com/download/manitou-access-platform-80-105vjr-service-sec-wat/>

0-1-M.85