



Volvo Truck Corporation

Göteborg, Sweden

Service Bulletin Trucks

Date	Group	No.	Release	Page
9.04	364	51	01	1(21)

The bulletin supplements Service Handbook Group 36 TSP20001275 "Fault codes vehicle control unit (VECU)"

Fault codes vehicle control unit (VECU)


MID 144

VERSION2

CHID A591628-

CHID B381169-

Fault codes MID 144



T3015744

Contents

- “MID 144 PID 84 Vehicle speed” page 3.
- “MID 144 PID 84 Vehicle speed, check” page 6.
- “MID 144 SID 250 SAE J1708 Information link” page 11.
- “MID 144 SID 253 Calibration memory EEPROM” page 12.
- “MID 144 PSID 20 Power take-off signal” page 14.
- “MID 144 PSID 20 Power take-off signal, check” page 16.
- “MID 144 PSID 21 CAN1” page 18.
- “MID 144 PSID 22 CAN2” page 19.
- “MID 144 PSID 230 Soft ware fault” page 20.
- “MID 144 PSID 232 J1939-2 Control link” page 21.

Volvo Trucks Mid 144 Engine Control Unit Fault Codes

Full download: <http://manualplace.com/download/volvo-trucks-mid-144-engine-control-unit-fault-codes/>

Volvo Truck Corporation

Service Bulletin

Date

9.04

Group

364

No.

51

Release

01

Page

2(21)

Malfuction