

# Zoomlion 20 Ton Operators Manual

Full download: <http://manualplace.com/download/zoomlion-20-ton-operators-manual/>



## ARTICULATED CRANE OPERATOR & SERVICE MANUAL



**This is the cut pages sample. Download all 20 page(s) at: [ManualPlace.com](http://ManualPlace.com)**

QLY20(420) 铰接式移动起重机  
QLY20(420) ARTICULATED CRANE

## 随机备件清单

## SPARE PARTS LISTS

QLY20(420). 30-2008

序号 No.	代号 CODE	名称 NAME	数量 QUANTITY	备注 REMARKS
1.	DS 18-L	卡套 cutting ferrule	10	
2.	DS 22-L	卡套 cutting ferrule	10	
3.	DS 28-L	卡套 cutting ferrule	2	
4.	GB3764-83 12	卡套 cutting ferrule	10	
5.	GB3764-83 10	卡套 cutting ferrule	10	
6.	GB3764-83 8	卡套 cutting ferrule	5	
7.	1128-E	螺母 nut	10	
8.	1128-E	螺母 nut	10	
9.	1128-E	螺母 nut	2	
10.	GB3759-83 G12	螺母 nut	10	
11.	GB3759-83 G10	螺母 nut	10	
12.	GB3759-83 G8	螺母 nut	5	
13.	GB1235-76 65*3.1	O型圈 O seal	2	
14.	GB1235-76 50*3.1	O型圈 O seal	2	
15.	GB3412-76 130*2.65	O型圈 O seal	1	
16.	JB982-77 22	组合垫 gland bush	20	
17.	JB982-77 27	组合垫 gland bush	10	
18.	JB982-77 18	组合垫 gland bush	10	
19.	JB982-77 16	组合垫 gland bush	10	
20.	504	易熔线 fusible links	2	
21.	504	易熔线 fusible links	4	
22.	JD97E-1813	继电器 relay	5	
23.	JQ6054	闪光器 flash apparatus	1	
24.	BT2001C-104	片式熔断器 fuse plug	1	
25.	BT2001C-105	片式熔断器 fuse plug	1	
26.	BT2001C-104A	片式熔断器 fuse plug	1	
27.	BT2001C-104	片式熔断器 fuse plug	1	